August 2023

Vickers® by Danfoss

Discontinuation of the Size 2 DG4V Directional Control Valve – August 2021

We regularly review our product offerings to ensure that they support our customers and are aligned with their needs. As a part of this process, we will be discontinuing our complete DG4V size 2 product portfolio (spare coils included), thus permitting greater focus on our newer product offerings.

Unfortunately, no alternatives exist within our portfolio. There is the option to switch to the size 3 DG valves, but with the associated changes in dimensions and performance.

All existing open orders will still be delivered, but no new orders will be accepted.

With immediate effect, the following part numbers are being made obsolete:

Complete valve part numbers	
Item number	**Model code**
02-311349	DG4V 2 2AL M U EJ6 10
02-312418	DG4V 2 6C VM U H6 10
02-318513	DG4V 2 2B M U DJ6 10
02-319442	DG4V 2 2AL M U HL6 10
02-332118	DG4V 2 8B VM U H6 10
02-333176	DG4V 2 6C M KUP6 G6 10
02-333543	DG4V 2 0C V M U EJ6 10
02-333737	DG4V 2 0C V M U DJ6 10
02-351446	DG4V 2 2AL VM U H6 10
02-351798	DG4V 2 0A VM U HL6 10
02-358609	DG4V 2 2AL M U DJ6 10
02-359250	DG4V 2 2C VM U H6 10
02-359382	DG4V 2 0AL M U H6 10

Spare coil part numbers
873706
873767
873768
874412
944690

Service policy

For warranty enquiries, please contact your CSR to arrange for the affected product to be returned to Danfoss with an associated RMA. The claim will be raised as retain for credit, and after the appraisal we will inform you

about the result. If accepted, the claim will be closed, and a credit will be issued for the valve. If no fault is found, the part(s) will be returned to you.

For all inquiries, please contact IMCProductSupport@danfoss.com.